

## Treatment of a wrist fracture related edema with manual lymphatic drainage and LymphaTouch therapy device



Patient's wrist before the treatment at 9:00 AM.



Patient's wrist after the treatment at 10:00 AM.



Patient's hand before the treatment at 9:00 AM.



Patient's hand after the treatment at 10:00 AM.

### The patient was treated:

#### With manual lymphatic drainage in the areas of

- neck
- shoulders
- intercostals
- armpit

#### With LymphaTouch therapy device in the areas of

- hand above the plaster cast
- back of the hand
- palm of the hand

### Treatment clinic:

Axis Ltd.  
Physical treatment practice  
MLD therapist Tuija Nikula  
Aninkaistenkatu 14 B  
20100 Turku  
Finland

[www.axisfysio.fi](http://www.axisfysio.fi)

**It is strictly prohibited to use the photos without a consent from the copyright owner.**