

LymphaTouch therapy method in the treatment of a patient with an open wound

In June 2008, the patient had a prescription for manual lymphatic drainage treatment in order to treat the oedema in the stump of the prostheses in his leg, and to heal the open wound in it. The patient was not, however, treated before April 2009.

Photo 1: The situation in June 11, 2009, before the patient was treated with LymphaTouch therapy device. The patient was by that time treated 9 times with manual lymphatic drainage therapy method. There was already less oedema in the patient's thigh and in the stump, and the open wound had gotten drier and smaller.

From mid-June onwards the patient was treated with LymphaTouch therapy method, and the wound started to get much smaller and the scars started to become much softer. With the LymphaTouch treatment device it was possible to get a feeling of suction also inside the stump of the leg. Despite the warm weather conditions during the last two weeks of the treatment period the swelling of the area of the wound could still be controlled. According to the feedback received from the patient the wound had never before been in as good condition as it was after the LymphaTouch treatments.

Photo 2: The situation in June 29, 2009. The area of the wound has diminished into size of appr. 10 mm x 5 mm. In addition, the scars surrounding the wound had softened. The open wound was measured a week earlier at the Turku University hospital department of dermatology. Due to the rapid healing progress, treatment at the hospital was no longer needed.



June 11, 2009



June 29, 2009

Treatment clinic:

Axis Ltd.
Physical treatment practice
MLD therapist Tuija Nikula
Aninkaistenkatu 14 B
20100 Turku
Finland

www.axisfysio.fi

It is strictly prohibited to use the photos without a consent from the copyright owner.